



XIGMATEK



# ODIN

The first silent optimized chassis  
with integrated performance mode

Accessory List	
	M/B screw X 12
	Copper Stand Off X 12
	Pan Washer Screw X 28
	PSU screw X 4
	SSD/HDD Screw X 28
	MB Stand Off Socket X 1
Front Fan Screw x 6	
Cable tie X 5	

**Installation Guide**



1.1 1.2

- Open front panel and side cover to begin installation
- Offenes Front Panel und Side Cover
- Öppna fram och sidluckorna
- Abrir el panel frontal y el lateral
- 取り付けの準備フロントパネルとサイドパネルの取り外し
- Открыть лицевую и боковую панели
- 打開前面板與側蓋
- Yen kapaklı açınak
- Ouvrir le panneau avant (façade) et le panneau latéral pour commencer l'installation


1



2.1

- Power supply unit installation
- Powersupply Installation
- Installation av nätdelen
- Instalación de la Fuente de alimentación
- 電源ユニットの取り付け
- Установка блока питания
- 安装电源供应器
- Göç Kaynağı birimi montajı
- Installation de l'unité d'alimentation


2



3.1 3.2

- Motherboard installation
- Motherboard Installation
- Installation av moderkort
- Instalación de la placa base
- マザーボードの取り付け
- Установка материнской платы
- 安装主機板
- Anakart montajı
- Installation de la carte mère


3




4



6



7



8

10

Note: There is a triangle symbol on the connectors, that means "+/-" side.